W. H. COOLEY.
METHOD OF FORMING EXPANDED METAL.
APPLICATION FILED JUNE 29, 1908.

909,064. Patented Jan. 5, 1909. 28HEETS-SHEET 1. m G 1 CITG. 4  $d\iota$  $egin{array}{c|cccc} d&d&d&d\\ c&c&c&c&c&c\\ e&||a|&|a|&|a| \end{array}$ didi di di di TG. 5 INVENTOR:

## W. H. COOLEY. METHOD OF FORMING EXPANDED METAL.

APPLICATION FILED JUNE 29, 1908. Patented Jan. 5, 1909. 2 SHEETS-SHEET 2. 909,064. TG. 6 mm TG. 9 TG. 10 m Ì TG. 11

## UNITED STATES PATENT OFFICE.

WILLIAM H. COOLEY, OF BROCKPORT, NEW YORK.

## METHOD OF FORMING EXPANDED METAL.

No. 909,064.

Specification of Letters Patent.

Patented Jan. 5, 1909.

Application filed June 29, 1908. Serial No. 440,805.

To all whom it may concern:

Be it known that I, WILLIAM H. COOLEY, a citizen of the United States, and a resident of Brockport, in the county of Monroe and 5 State of New York, have invented a new and Improved Method of Forming Expanded Metal, of which the following is a specifica-

My present invention relates to an im-10 proved method of producing expanded metal such as used in reinforced concrete work and for lathing and other similar purposes.

It has been customary hitherto in the production of expanded metal, when the metal 15 was cut by reciprocating dies, to expand the metal as it is being cut, and when the metal was cut by means of rotary cutters, to expand the metal either while being cut or subsequently to the cutting operation in a sep-20 arate expanding apparatus or machine, in which latter case it has been usual to expand the entire sheet at one operation. This method has afforded some advantages, in that the entire sheet could be expanded at a 25 single operation and the cutting could be more rapidly done by means of rotary cut-

Machines for expanding the metal, after it has been cut, at a single and independent op-30 eration have usually been of such a size as to be seriously objectionable for the larger size sheets, as such machines had to be adapted to receive the sheet in its full dimensions in one direction before expansion and to ex-35 pand the metal to its maximum dimension in the transverse direction. In such machines it has been usual to place the entire strain of the expanding operation upon the opposite edges of the sheet and such expansion has 40 sometimes been somewhat irregular, owing to the fact the strain in the expanding operation is put upon strands or side bars of the meshes at the extreme edges of the sheet.

By means of my methed I am enabled to 45 greatly reduce the expense of and the space occupied by the expanding apparatus while securing at the same time a nearly perfect regularity in the shape and size of the mesh in the expanded metal.

In carrying out my invention, I first form the cuts in the metal in the desired way by means of, preferably rotary, cutters, although reciprocating cutters may be used, and as the metal leaves the cutters, it is 55 caused to pass through crimping or corrugating mechanism, which may also be pref-

erably of the rotary type, although reciprocating mechanism may be used for this purpose also, which crimps the sheet in such a way that a strip cut from the sheet trans- 60 versely of the corrugations and of the direction of the feed through the cutters will correspond to the dividing wall or bars between two adjacent and transversely extending series of meshes, so that to produce the ex- 65 panded metal, it is only necessary to bend every other series of bars, between the cuts, in the opposite direction from that in which they lie in the crimped or corrugated sheet, and in expanding such a sheet it is only 70 necessary to engage the sheet at the keys between the bars and draw such keys in straight lines without stretching the metal.

I desire to call especial attention to the fact that one of the essential features of my 75 present invention consists in so crimping the sheet after it has been cut that the direction of the motion of the expanding members may be in straight lines, on account of which the metal may be expanded without 80 stretching and the expander may be comparatively small and simple in construction,comprising either a roller having engaging teeth on it or a pair of rollers carrying sprocket chains or other endless bands hav- 85 ing engaging teeth thereon, such teeth spaced the same distance each way as the keys in the expanded metal. By this method of expansion, the meshes are all expanded uniformly and each mesh is ex- 90 panded independently of any other mesh in

An important feature of my present invention is the cutting of the metal by rotary cutters, as such cutters may be operated 95 with greater rapidity than reciprocating dies, and for the further reason that such rotary cutters may be advantageously incorporated in the same machine with the crimping or corrugating rollers and the 100 sheet may be delivered from such machine in its cut and corrugated or crimped form.

Another important feature of my invention is the character and method of forming the cuts in the metal, the purpose being to 105 provide a system of cutting in which rotary cutters may be used whose outer peripheries are plain and in no way notched, such cutters operating to displace from the normal initial plane of the sheet longitudinally extending portions whose width is the width of one of the bars inclosing the meshes in the

expanded metal, such longitudinally extending strips located alternately below and above the normal initial plane of the metal and adjacent ones of such alternating strips 5 separated by an intermediate strip of the same width but extending first above and then below the initial plane of the metal and united to such first named strips on each side thereof at points denominated keys in 10 the finished product. In cutting the metal in this way the centrally disposed longitudinally extending strips are connected to alternately positioned keys in rows extending transversely of the metal.

The accompanying drawings illustrate different steps in my process of forming the expanded metal and diagrammatically the apparatus which I may make use of for carrying out this process or method. Such

20 drawings are as follows:-

Figure 1 shows in end view and partially in section a pair of cooperating cutting rollers. Fig. 2 shows an enlarged view of these rollers at the cutting points and with a sheet 25 of metal as passing therethrough and a portion of the sheet of metal as having been cut by the Fig. 3 is a sectional view of the cutting rollers near their cooperating outer edges. Fig. 4 shows diagrammatically the cutsformed 30 by the rotary cutters. Fig. 5 shows in diagram the cutting rollers and the coöperating feed rollers and additional thereto the crimping or corrugating rollers, while Fig. 6 shows in enlarged view a portion of the corrugating 35 rollers and a part of a sheet of metal being operated on thereby. Fig. 7 shows a plan view of the metal after it has been cut and corrugated. Fig. 8 shows a section of the expanded metal and diagrammatically the 40 positions of the expanding fingers as they expand the metal. Fig. 9 is a top view of a portion of the expanding mechanism, while Fig. 10 is a side view of the expander. Fig. 11 shows a modified form of the expanding 45 mechanism

Similar letters refer to similar parts throughout the different figures of drawing. Referring to Figs. 1, 2, 3 and 4,—my rotary cutters consist of a series of plain upper 50 and lower disks a and a', the face or thickness of which is the width between the cuts and the width of a bar in the expanded metal. These disks a and  $a^1$  are assembled on suitable shafts and held properly spaced 55 in a way to be explained and the thickness also of a bar apart between a disk a and a These disks a and  $a^1$  overlap each other and by just twice that distance which the longitudinally extending strips are to be 60 displaced from the initial plane of the metal. On each side of each roller a is a cutter c and on each side of each such roller  $a^1$  is a cutter c1, the extreme outer peripheries of the cutters c and c1 presenting series of cutting seg-

the adjacent side of a disk a, while a cutter ccuts against the adjacent side of a disk  $a^1$ , such cutters c and c1 having their more prominent edges even with the disks a and a1, respectively. Cutting edges on the rotary cut- 70 ters c and c1 are alternately positioned and are adapted to force the metal from the normal initial plane of the sheet first upwardly to a point in alinement with the outer periphery of a disk  $a^1$  and then downwardly to 75 a point in line with the outer periphery of a disk a. The cutters c are separated first by a disk a and then by a spacing disk d and in a similar way the cutters  $c^1$  are separated first by a disk  $a^1$  and a spacing disk  $d^1$ . The 80 thickness of these spacing disks it will be noted is of course the same as that of the cutters and other disks. The cutting disks cand c1 after they have operated on the metal leave cuts and forced from the initial plane of 85 the sheet a series of sections arranged, as indicated clearly in edge view in Fig. 2, the cuts being arranged as indicated in Fig. 4. As seen in Fig. 5, feed rollers F and F<sup>1</sup> and G and G<sup>1</sup> are provided each side of the rotary 90 cutters and the metal is supposed to pass from left to right, in this figure, and as it leaves the roller G it is flattened out again.

After passing through the feed rollers G and  $G^1$ , the sheet of metal m is engaged by a 95 coöperating pair of crimping or corrugating rollers P and P1, the size and rate of rotation of which is such as to substantially take up the travel of the sheet through the preceding rollers and cutters. These rollers P and P<sup>1</sup> 100 form in the sheet transversely arranged corrugations conforming to the contour of the mesh in the expanded metal, in the centers of which are located the keys in transversely extending rows, every other row of keys be-ing forced in one direction and every intermediate row of keys being forced in the opposite direction from the initial plane of the sheet. Such a sheet of metal when thus corrugated is next expanded by being inserted between 110 two guides h and  $h^1$  having connecting end pieces  $h^2$ , only one of which is seen, and one, and preferably the right hand, series of keys is engaged by a series of projecting fingers t extending outwardly from each one of a se- 115 ries of bars b secured upon an endless band or carrier B and caused to rotate over the rollers E and E1. These rollers E and E1 carry on their ends a series of teeth e adapted to engage the bars b to propel the same in the ex- 120 panding operation. In the expanding of the metal by this mechanism, the keys in the cut and corrugated metal are drawn in straight lines and the completed mesh, of diagonal form, is produced by drawing the metal at the 125 keys in straight lines and without stretching, as clearly indicated. By reason of the corrugation of the metal, one half of the side walls of each series of transversely arranged meshes 65 ments so formed that a cutter c1 cuts against | in the expanded metal is already formed to 130

909,064

shape, while the connecting bars for the opposite halves of each one of such series of transversely disposed meshes is formed by bending such bars in the opposite direction 5 from that in which they lie in the crimped and corrugated metal between the members hand  $\hbar^1$ .

Instead of the form of expander shown in Figs. 9 and 10, I may use the modified form 10 shown in Fig. 11, in which instance, in place of the fingers t I may use similar fingers  $t^1$  projecting directly from the single rotating cyl-

inder E<sup>3</sup>.

I desire to call attention to the fact that 15 each mesh is expanded by itself and that the expansion is effected without stretching the metal and is uniform throughout the sheet regardless of any slight irregularities in the spacing of the cuts or in the 20 character of the metal, and also to the fact that in the expansion only every other series of bars is bent in the opposite direction from that in which it lies in the cut and crimped metal, while every intermediate series of 25 bars is simply moved along in its normal shape or condition without bending. On account of the crimping or corrugating of the metal, permitting the expanding fingers t to travel in straight lines, the expand-30 ing process may be a continuous and rapid one and effected by the simple mechanism

Any suitable feeding mechanism may be used to feed the corrugated sheet into engage-35 ment with the expanding mechanism and I have shown only diagrammatically one form of such a feeding mechanism in Figs. 8 and 10. Such a feeding mechanism may comprise a weight w having attached thereto a chain or 40 rope r arranged to pass over a pulley O secured upon a shaft o and revoluble in bearings v and such chain secured at its other end to a plate u engaging under the under edge or end of the corrugated sheet 45 of metal, as indicated. There may be any desired number of such weights and ropes and pulleys, according to the length of the sheet transversely of the corrugations. There should be provided at least two such 50 weights one having its attaching cord se-

cured to each end of the cross bar u.

What I claim is:

1. The within described method of cutting metal for expansion which consists in 55 forming alternating series of interrupted cuts in the metal to leave alternating keys between the cuts and simultaneously forcing continuously in one direction away from the initial plane of the sheet longitudinally 60 extending strips between the cuts spaced part by three intermediate strips and forcing the centrally disposed one of each such three intermediate strips continuously in the opposite direction away from the initial oss plane of the sheet and forcing the adjacent sists in first corrugating the sheet to shorten 130

strip on each side of each such centrally disposed intermediate strip obliquely across the initial plane of the sheet between their alternating connections at the keys to strips on each side thereof forced continuously in 70

opposite directions.
2. The within described method of cutting metal for expansion which consists in forming alternating series of interrupted cuts in the metal to leave alternating keys 75 between the cuts and simultaneously forcing continuously in one direction away from the initial plane of the sheet longitudinally extending strips between the cuts spaced apart by three intermediate strips and forc- 80 ing the centrally disposed one of each such three intermediate strips continuously in the opposite direction away from the initial plane of the sheet and forcing the adjacent strip on each side of each such centrally 85 disposed intermediate strip obliquely across the inital plane of the sheet between their alternating connections at the keys to strips on each side thereof forced continuously in opposite directions, the obliquely extending 90 connecting strips on one side of each such centrally disposed intermediate strip alternating in direction with those on the other side of such centrally disposed intermediate

3. The within described method of forming expanded metal, which consists in forming alternating series of interrupted cuts in the metal to leave alternating keys between the cuts and forcing every other row of keys 100 in one direction away from the normal plane of the metal and every intermediate row of keys in the opposite direction to form in the cut or slashed metal corrugations extending transversely of the cuts, the contours of 105 which correspond substantially to the contours of any two bars on the same side of a mesh with the connecting key between them in the expanded metal and engaging the corrugated sheet at the keys and drawing 110 the same in substantially parallel and straight lines extending substantially in a plane at an angle to the plane of the cor-

rugated sheet.

4. The within described method of ex- 115 panding a slashed sheet of metal, which consists in forming in the slashed or cut metal corrugations extending transversely of the cuts, the contours of which correspond substantially to the contours of any two bars 120 on the same side of a mesh with the connecting key between them in the expanded metal and engaging the corrugated sheet at such keys and drawing the same in substantially parallel and straight lines extending sub- 125 stantially in a plane at an angle to the plane of the corrugated sheet.

5. The within described method of expanding a slashed sheet of metal which con-

the sheet in the direction of the cuts to per-.nit the expansion of the sheet by opening the cuts therein by forcing or drawing points correspondingly located on opposite sides of the 5 cuts relatively apart in planes perpendicular to the original direction of the cuts and parallel to each other and then forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart in 10 planes perpendicular to the original direc-tion of the cuts and parallel to each other.

6. The within described method of forming expanded metal, which consists in forming alternating series of interrupted cuts in 15 the metal to leave alternating keys between the cuts and forcing every other row of keys in one direction from the normal plane of the metal and every intermediate row of keys in the opposite direction to form in the cut or 20 slashed metal corrugations extending transversely of the cuts, the contours of which correspond substantially to the contours of any two bars on the same side of a mesh with the connecting key between them in the 25 expanded metal and engaging the corrugated sheet at the keys and drawing the same in substantially parallel and straight lines to expand the sheet.

7. The within described method of ex-30 panding a slashed sheet of metal, which consists in forming in the slashed or cut metal corrugations extending transversely of the cuts, the contours of which correspond substantially to the contours of any two bars on 35 the same side of a mesh with the connecting key between them in the expanded metal and engaging the corrugated sheet at the keys and drawing the same in substantially parallel and straight lines to expand the

40 sheet.

8. The within described method of expanding a slashed sheet of metal which consists in first corrugating the sheet to shorten the sheet in the direction of the cuts to per-45 mit the expansion of the sheet by opening the cuts therein by forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart in substantially straight lines in planes perpendicular to the 50 original direction of the cuts and then forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart in substantially straight lines in planes per-pendicular to the original direction of the 55 cuts.

9. The within described method of forming expanded metal, which consists in forming alternating series of interrupted cuts in the metal to leave alternating keys between 60 the cuts and forcing every other row of keys in one direction away from the normal plane of the metal and every intermediate row of keys in the opposite direction to form in the cut or slashed metal corrugations extending 65 transversely of the cuts, the contours of key between them in the expanded metal 130

which correspond substantially to the contours of any two bars on the same side of a mesh with the connecting key between them in the expanded metal, and engaging the corrugated sheet at the keys and drawing the 70 same in substantially parallel and straight lines extending substantially in a plane transverse to the plane of the corrugated sheet.

10. The within described method of ex- 75 panding a slashed sheet of metal which consists in forming in the slashed or cut metal corrugations extending transversely of the cuts, the contours of which correspond substantially to the contours of any two bars on 80 the same side of a mesh with the connecting key between them in the expanded metal and engaging the corrugated sheet at such keys and drawing the same in substantially parallel and straight lines extending substan- 85 tially in a plane transverse to the plane of the

corrugated sheet.

11. The within described method of expanding a slashed sheet of metal which consists in first corrugating the sheet to shorten 90 the sheet in the direction of the cuts to permit the expansion of the sheet by opening the cuts therein by forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart in substantially 95 straight lines in planes perpendicular to the original direction of the cuts and parallel to each other and then forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart in substan- 100 tially straight lines in planes perpendicular to the original direction of the cuts and parallel to each other.

12. The within described method of forming expanded metal, which consists in form- 105 ing alternating series of interrupted cuts in the metal to leave alternating keys between the cuts and forcing every other row of keys in one direction away from the normal plane of the metal and every intermediate row of 110 keys in the opposite direction to form in the cut or slashed metal corrugations extending transversely of the cuts, the contours of which correspond substantially to the contours of any two bars on the same side of a 115 mesh with the connecting key between them in the expanded metal and engaging the corrugated sheet at the keys and drawing the same substantially without stretching the metal in substantially parallel and straight 170 lines extending substantially in a plane at an angle to the plane of the corrugated sheet.

•13. The within described method of ex panding a slashed sheet of metal, which con sists in forming in the slashed or cut metal 175 corrugations extending transversely of the cuts, the contours of which correspond substantially to the contours of any two bars on the same side of a mesh with the connecting

and engaging the corrugated sheet at such | keys and drawing the same substantially without stretching the metal in substantially parallel and straight lines extending substan-5 tially in a plane at an angle to the plane of

the corrugated sheet.

14. The within described method of expanding a slashed sheet of metal which consists in first corrugating the sheet to shorten 10 the sheet in the direction of the cuts to permit the expansion of the sheet by opening the cuts therein by forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart in planes perpendic-15 ular to the original direction of the cuts and parallel to each other and then forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart substantially without stretching the metal in 20 planes perpendicular to the original direction

of the cuts and parallel to each other. 15. The within described method of forming expanded metal, which consists in forming alternating series of interrupted cuts in 25 the metal to leave alternating keys between the cuts and forcing every other row of keys in one direction away from the normal plane of the metal and every intermediate row of keys in the opposite direction to form in the 30 cut or slashed metal corrugations extending transversely of the cuts, the contours of which correspond substantially to the contours of any two bars on the same side of a mesh with the connecting key between them 35 in the expanded metal and engaging the corrugated sheet at the keys and drawing the same substantially without stretching the metal in substantially parallel and straight lines to expand the sheet.

16. The within described method of expanding a slashed sheet of metal which consists in forming in the slashed or cut metal corrugations extending transversely of the cuts, the contours of which correspond sub-45 stantially to the contours of any two bars on the same side of a mesh with the connecting key between them in the expanded metal and engaging the corrugated sheet at the keys and drawing the same substantially without 50 stretching the metal in substantially parallel and straight lines to expand the sheet.

17. The within described method of expanding a slashed sheet of metal which consists in first corrugating the sheet to shorten 55 the sheet in the direction of the cuts to permit the expansion of the sheet by opening the cuts therein by forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart in substantially straight lines in planes perpendicular the opinion dispation of the cuts and to the original direction of the cuts, and then forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart substantially without 65 stretching the metal in substantially straight | two bars on the same side of a mesh with the 130

lines in planes perpendicular to the original direction of the cuts.

18. The within described method of forming expanded metal, which consists in forming alternating series of interrupted cuts in 70 the metal to leave alternating keys between the cuts and forcing every other row of keys in one direction away from the normal plane of the metal and every intermediate row of keys in the opposite direction to form in the 75 cut or slashed metal corrugations extending transversely of the cuts. the contours of which correspond substantially to the contours of any two bars on the same side of a mesh with the connecting key between 80 them in the expanded metal and engaging the corrugated sheet at the keys and drawing the same substantially without stretching the metal in substantially parallel and straight lines extending substantially in a 85 plane transverse to the plane of the corrugated sheet.

19. The within described method of expanding a slashed sheet of metal which consists in forming in the slashed or cut metal 90 corrugations extending transversely of the cuts, the contours of which correspond substantially to the contours of any two bars on the same side of a mesh with the connecting key between them in the expanded metal 36 and engaging the corrugated sheet at such keys and drawing the same substantially without stretching the metal in substantially parallel and straight lines extending substantially in a plane transverse to the 100

plane of the corrugated sheet.

20. The within described method of expanding a slashed sheet of metal which consists in first corrugating the sheet to shorten the sheet in the direction of the cuts to per- 105 mit the expansion of the sheet by opening the cuts therein by forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart in substantially straight lines in planes perpendicular 110 to the original direction of the cuts and parallel to each other and then forcing or drawing points correspondingly located on opposite sides of the cuts relatively apart substantially without stretching the metal in 115 substantially straight lines in planes per-pendicular to the original direction of the cuts and parallel to each other.

21. The within described method of forming expanded metal which consists in forming 120 alternating series of interrupted cuts in the metal to leave alternating keys between the cuts and forcing every other row of keys in one direction away from the normal plane of the metal and every intermediate row of keys 125 in the opposite direction to form in the cut or slashed metal corrugations extending transversely of the cuts, the contours of which correspond substantially to the contours of any

connecting key between them in the expanded metal and forcing or bending every other transversely extending row of bars in the opposite direction from that in which they lie in

5 the corrugated sheet.

22. The within described method of expanding a slashed sheet of metal which consists in forming in the slashed or cut metal corrugations extending transversely of the cuts the contours of which correspond substantially to the contours of any two bars on the same side of a mesh with the connecting key between them in the expanded metal and forcing or bending every other transversely extending row of bars in the opposite direction from that in which they lie in the corrugated sheet.

23. The within described method of forming expanded metal which consists in forming alternating series of interrupted cuts in the metal to leave alternating keys between the cuts and forcing every other row of keys in one direction away from the normal plane of the metal and every intermediate row of keys in the opposite direction to form in the cut or slashed metal corrugations extending trans-

versely of the cuts, the contours of which correspond substantially to the contours of any two bars on the same side of a mesh with the connecting key between them in the expandaded metal and forcing or bending substantially without stretching the metal every other transversely extending row of bars in the opposite direction from that in which they lie in the corrugated sheet.

24. The within described method of expanding a slashed sheet of metal which consists in forming in the slashed or cut metal corrugations extending transversely of the cuts, the contours of which correspond substantially to the contours of any two bars on the same side of a mesh with the connecting key between them in the expanded metal and forcing or bending substantially without stretching the metal every other transversely extending row of bars in the opposite direction from that in which they lie in the corrugated sheet.

WM. H. COOLEY.

Witnesses:

OSBORNE F. GURNEY, LOTTIE WOOD.