



ABSTRACT

A galvanized steel sheet contains, by % by mass, 0.05 to 0.25% of C, 2.0% or less of Si, 1 to 3% of Mn, 0.1% or less of P, 0.01% or less of S, 0.3 to 2% of Al, less than 0.005% of N, 1% or less of Cr, 1% or less of V, 1% or less of Mo, less than 0.005% of Ti, and less than 0.005% of Nb, and satisfies the relations, $Si + Al \geq 0.6\%$ and $Cr + V + Mo = 0.1$ to 2%, the balance being Fe and inevitable impurities.

