



US00D340171S

United States Patent [19] Vigil

[11] Patent Number: **Des. 340,171**
[45] Date of Patent: **** Oct. 12, 1993**

[54] WINDSHIELD REPAIR KIT

[76] Inventor: **Michael S. Vigil**, P.O. Box 4381,
Highlands Ranch, Colo. 81026

[**] Term: **14 Years**

[21] Appl. No.: **802,761**

[22] Filed: **Dec. 9, 1991**

Related U.S. Application Data

- [63] Continuation-in-part of Ser. No. 608,847, Nov. 5, 1990, abandoned.
- [52] U.S. Cl. **D8/30; D24/130**
- [58] Field of Search **D8/29.1, 30; D24/130; 604/192-198, 110, 125, 202, 203, 208, 201**

[56] **References Cited**

U.S. PATENT DOCUMENTS

- D. 245,474 8/1977 Scholl D8/30
- D. 315,852 4/1991 Nusse et al. D8/30
- D. 321,759 11/1991 Boswell D24/130
- 5,007,903 4/1991 Ellard 604/195

Primary Examiner—Alan P. Douglas
Assistant Examiner—J. H. Musgrove
Attorney, Agent, or Firm—Leon Gilden

[57] **CLAIM**

The ornamental design for a windshield repair kit, as shown and described.

DESCRIPTION

FIG. 1 is a front elevational view of the windshield repair kit showing my new design;
FIG. 2 is a rear elevational view thereof;
FIG. 3 is a left side elevational view thereof;
FIG. 4 is a right side elevational view thereof;
FIG. 5 is a top plan view thereof; and,
FIG. 6 is a bottom plan view thereof.





FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6

