



US0D1017983S

(12) **United States Design Patent**  
**Morgan**

(10) **Patent No.:** **US D1,017,983 S**

(45) **Date of Patent:** **\*\* Mar. 19, 2024**

- (54) **TOE THONG PLUG**
- (71) Applicant: **HERE’S GOLDEN LTD.**, Auckland (NZ)
- (72) Inventor: **Simon Morgan**, Auckland (NZ)
- (73) Assignee: **HERE’S GOLDEN LTD.** (NZ)
- (\*\*) Term: **15 Years**

- (21) Appl. No.: **29/796,053**
- (22) Filed: **Jun. 22, 2021**
- (51) **LOC (14) Cl.** ..... **02-04**
- (52) **U.S. Cl.**  
USPC ..... **D2/946**
- (58) **Field of Classification Search**  
USPC ..... D2/896–900, 902, 906–909, 913, 917,  
D2/919, 943–947, 952, 957–958, 962,  
D2/969, 972–974, 976–978  
CPC .... A43B 1/04; A43B 3/10; A43B 5/06; A43C  
7/00; A43C 11/006; A43C 11/14; A43C  
7/02; A43C 7/06  
See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D177,486 S *	4/1956	Stile .....	D2/917
D393,537 S *	4/1998	Johnson .....	D2/906
D578,299 S *	10/2008	Dennis .....	D26/1
D604,940 S *	12/2009	Collier .....	D2/976
D655,493 S *	3/2012	Kelley .....	D2/978
D664,747 S *	8/2012	Ma .....	D2/917
D733,408 S *	7/2015	Franco .....	D2/976

D808,627 S *	1/2018	Kohatsu .....	D2/962
D818,675 S *	5/2018	Stonisch .....	D2/976
D909,041 S *	2/2021	Sears .....	D2/976
D986,574 S *	5/2023	Tja .....	D2/976
D990,864 S *	7/2023	Mariott .....	D2/976
D991,647 S *	7/2023	Walsh .....	D2/946
D997,545 S *	9/2023	Xi .....	D2/978
D1,003,024 S *	10/2023	Strek .....	D2/962

\* cited by examiner

*Primary Examiner* — Michelle E. Wilson

*Assistant Examiner* — Clare Ann Gannon

(74) *Attorney, Agent, or Firm* — Eric Karich; KARICH & ASSOCIATES

(57) **CLAIM**

The ornamental design for a toe thong plug, as shown and described.

**DESCRIPTION**

FIG. 1 is a perspective view of a toe thong plug, showing the new design;

FIG. 2 is a front elevation view thereof, shown with the unclaimed toe thong removed for convenience of illustration;

FIG. 3 is a rear elevation view thereof;

FIG. 4 is a left side elevation view thereof;


FIG. 5 is a right side elevation view thereof;

FIG. 6 is a top plan view thereof; and,

FIG. 7 is a bottom plan view thereof.

The evenly broken lines depict portions of the article that form no part of the claimed design. The dot-dash broken line in FIG. 1 indicated that the remainder of the unclaimed toe thong is broken away.

**1 Claim, 3 Drawing Sheets**









FIG. 1




*FIG. 2*




*FIG. 3*




*FIG. 4*



*FIG. 5*



*FIG. 6*



*FIG. 7*